

A photograph of a geological field site. In the foreground, a large, light-brown, layered rock sample is visible, showing signs of weathering and fracturing. A black arrow points to a specific crack in the rock. To the right, a silver and black geological compass is placed on the rock surface. The compass has a circular dial with degree markings from 0 to 360 and cardinal directions (N, E, S, W). The background consists of more rugged, darker rock formations and some soil.

GEOTECNIA

GEA
ASESORÍA GEOLÓGICA



GEOTECNIA

Tipos de estudios

GEOLÓGICOS - GEOTÉCNICOS

CARTOGRÁFICOS

HIDROGEOLÓGICOS

ESTABILIDAD DE TALUDES

PERITAJES

CONTAMINACIÓN DE SUELOS





Polígono de Silvota
c/Peña Beza, Nave 16
33192 Llanera (Asturias)
T. 985 227 543
F. 985 204 793

correo@geaasesoriageologica.com

www.geaasesoriageologica.com